




1-800-248-0280
831 Morley Drive
Saginaw, MI 48601

DETAIL E2070



Note 1: Back seal and fasten top flange of collector 6-inches on center. Apply a bead of approved sealant on top of flange.

DATE: JANUARY 2013

DRAINAGE DETAILS

DRAWN BY: ENG. DEPT.

VINYL-BACK COLLECTOR W/SCUPPER

SCALE: NONE

NEW CONSTRUCTION OR RE-ROOF